

Advisory: Kidde Smoke Alarms Recalled



More than 450,000 Kidde dual-sensor smoke alarms have been recalled because a manufacturing error left a yellow cap over one of the units' two smoke sensors. The recall affects two models: the PI2010 (hard-wired) and PI9010 (battery powered).

Owners are advised to inspect their detectors through the opening on the side. Do not take units apart. Model number and date code are printed on the back of the alarm. If a yellow cap is present, contact Kidde for further instructions and a free replacement alarm. If no yellow cap is present, the alarm is safe to reinstall.

Contact Kidde toll free at 833-551-7739 from 8:30 a.m. to 5 p.m. ET Monday through Friday, and from 9 a.m. to 3 p.m. Saturday and Sunday. For more information, or to register your affected unit for a replacement, go to Kidde website by [clicking HERE](#), then click "Product Safety Recall."